



DEAD END WATERMAINS SHALL TERMINATE WITH ONE OF THE FOLLOWING METHODS ADEQUATE RESTRAINT SHALL BE USED PRIOR TO THE REDUCER OR TEE RESTRAINT SHALL BE M.J. PIPE OR OTHER METHODS APPROVED BY THE ENGINEER. VALVES SHALL BE RODDED TO THE REDUCER OR TEE.




OPTION 1:

HYDRANT WITH REDUCER



OPTION 2:

HYDRANT WITH TEE & PLUG



CITY OF WYOMING  
ENGINEERING DEPARTMENT

DEAD END WATERMAIN DETAIL

DRAWN BY - MW

CHECKED BY - RH

DATE DRAWN- 2-07-2005

DATE REVISED-

**W-24**